
## **Entrance**





# Responsibilities





# Occupational safety is always top priority!



### Warning



Warning -Risk of Falling



Warning -

Obstacles

Warning -Warning -Forklift Traffic Danger Area



Warning -Suspended Loads



Wear Protective Clothing



Wear Safety Footwear



**Construction Site Safety** 

Wear Head Protection



Wear a High-Vis Jacket

### **Prohibitions**



No Access for **Unauthorised Persons** 



No Photography by **Unauthorised Persons** 



Use Fall Protection Equipment (if necessary)



Wear Eye Protection



Use Respiratory Protection Equipment (if necessary)





### **Emergency Phone Numbers**

- » Via plant landline telephone: 115
- » Via mobile phone: +49 40 7883-3115

## PPE Standards for the FSH24 Maintenance Shutdown Adurubis



PPE Matrix for the "FSH24 Maintenance Shutdown" project	Safety Goggles	Lightweight Safety Glasses	Respiratory Protection	Protective Work Clothing	Safety Footwear	Helmet	High-Vis Jacket
Locker room, up until site access	_	_	_				
KB1 – Waste heat boiler							
KB2 – Flash smelting furnace	Permissible combinations in areas KB1 to KB6 and KB8:  Airstream helmet (visor folded down); lightweight safety glasses with visor folded up			✓ Standard (Basic) PPE on the entire Aurubis plant premises			
KB3 – Flash smelting furnace flue gas tract							
KB4 – Converter							
KB5 – Anode furnace/Anode casting wheel							
KB6 – Drying							
KB8 – Matte Settling Furnace & Granulation							
KB7 – East Plant Contact Plant	1	_	_				
Road 010	_	1	_				
Pre-assembly stations	_	1	_				

» In the case of activities subject to permit obligations, PPE must be worn in accordance with the permit specifications. In addition, safety gloves must be worn in accordance with the respective hazard level, and hearing protection must be worn when performing noise-intensive activities.