

CuZn15

EN_2024_06

Comparable standards: Aurubis designations: UNS C23000 • EN CW502L • JIS C2300 C230 • PNA 223

Description

CuZn15 is a solid solution strengthened copper alloy containing 15% zinc (brass). CuZn15 has very good cold fomability and is suited for bending, stamping and other cold forming processes. The alloy may be soldered, brazed or welded.

As the zinc content increases, the strength improves, yet the conductivity and ductility are reduced. CuZn15 has a good resistance to stress corrosion cracking, yet the alloy should be stress relieved if exposed to an ammonia atmosphere.

Due to the raised zinc content brass has economical advantages.

CuZn15 is a widely used alloy with an excellent combination of strength, ductility and corrosion resistance.

Composition

Cu	Fe	Pb	Zn	AI	Ni	Sn
[%]	[%]	[%]	[%]	[%]	[%]	[%]
84-86	0.05 max	0.05 max	rem	0.02 max	0.3 max	0.1 max

Composition of this alloy is in accordance with RoHS for electric & electronic components and ELV for the automotive industry.

Physical properties

Melting point	Density	с _р @ 20°С	Young's modulus	Thermal cond.	Electrical cond.		α @20-300°C	
[°C]	[g/cm ³]	[kJ/kgK]	[GPa]	[W/mK]	[MS/m]	[%IACS]	[10 ⁻⁶ /K]	
1027	8.75	0.38	122	159	≥21	≥36	18.7	

Note: The specified conductivity applies to the soft condition only.

 $\boldsymbol{c}_{\boldsymbol{p}}$ specific heat capacity

 $\boldsymbol{\alpha}$ coefficient of thermal expansion

Mechanical properties

	Tensile Strength	Yield Strength	Elongation A ₅₀	Hardness HV	Bend ratio 90° [r]		Bend ratio 180° [r]	
	[MPa]	[MPa]	[%]	[-]	GW	BW	GW	BW
R260	260-310	≤ 170	≥ 36	55-85	0	0	0	0
R300	300-370	≥ 150	≥ 16	85-115	0	0	0	0
R350	350-420	≥ 250	≥ 4	105-135	0	0	0	0
R410	410-490	≥ 360	≥ 2	125-155	0	1	0.5	1
R480	480-560	≥ 430	≥ 1	≥ 150	0.5	3	1	3.5
R550	≥ 550	≥ 500	-	-	0.5	1.5	1	3
	$r = v \star t$ (this/noos $t < 0$ Fmm)							

r = x * t (thickness t ≤ 0.5mm)

GW bend axis transverse to rolling direction. BW bend axis parallel to rolling direction.

Material Datasheet CuZn15



Hot formability	good				
Soldering	excellent				
Brazing	excellent				
Oxyacetylene welding	good				
Gas shielded arc welding	good				
Resistance welding	fair				
Machinability	fair				
 The electrical conductivity depends on chemical composition, the level of cold deformation and the grain size. A high level of deformation as well as a small grain size decrease the conductivity. Brass is resistant to: Natural, industrial and salt bearing atmospheres, drinking water, alkaline and neutral saline solutions. Brass is not resistant to: Acids, ammonia, halogenide, cyanide and hydrogen sulfide solutions and atmospheres as well as sea water (especially at high flow rates). CuZn15 has a low sensitivity to stress corrosion cracking and is resistant to dezincification, different to brass alloys with higher zinc contents. Yet the alloy should be stress relieved if stress corrosion cracking might be an issue. 					
	Brazing Dxyacetylene welding Gas shielded arc welding Resistance welding Machinability The electrical conductivity depends on o the grain size. A high level of deformatic conductivity. Brass is resistant to: Natural, industrial a and neutral saline solutions. Brass is not resistant to: Acids, ammoni and atmospheres as well as sea water (CuZn15 has a low sensitivity to stress c different to brass alloys with higher zinc	Brazing excellent Oxyacetylene welding good Gas shielded arc welding good Resistance welding fair Machinability fair The electrical conductivity depends on chemical composition, the level of cold deformation the grain size. A high level of deformation as well as a small grain size decrease the conductivity. Brass is resistant to: Natural, industrial and salt bearing atmospheres, drinking water, alka and neutral saline solutions. Brass is not resistant to: Acids, ammonia, halogenide, cyanide and hydrogen sulfide solutiand atmospheres as well as sea water (especially at high flow rates). CuZn15 has a low sensitivity to stress corrosion cracking and is resistant to dezincification different to brass alloys with higher zinc contents. Yet the alloy should be stress relieved if			

Typical usesArchitectural, stamped and deep drawn products, jewelry, dry goods, comsmetic packaging,
components of electrical engineering, mechanical and building engineering.

This leaflet is for general information only and is not subject to revision. No claims can be derived from it unless there is evidence of intent or gross negligence. The data given are no warranty that the product is of a specified quality and they cannot replace expert advice or the customer's own test.